


OCESD#1
Private Fire Line/Sprinkler Underground Process
Flow Chart



1. Visual Inspection must be completed prior to ceiling completion.
2. It is recommended that the hydrostatic test be completed prior to ceiling cover. If the hydrostatic test fails, the ceiling areas already covered may be required to be uncovered.
3. Additional protection and/or changes may be required based upon field inspection